
WIRING DIAGRAM
FOR CONNECTION OF THE GAS INJECTION SYSTEM FOBOS 2



WARNING

The gas injector connector marked A must correspond to the BLUE wire of the injector cut-off cable.